




ATLAS Level-1 Calorimeter Trigger




CP/JEP ROD Prototype Test Status

Infinite and countable?

B.M. Barnett, Rutherford Appleton Laboratory
Collaboration Meeting. November 7-10, 2001




Overview



- Mandate
- Test Setups (2)
- Fault Status
- Keeping Track of the Fixes
- Where next?




Mandate





- Test CP/JEP ROD functionality
 - CP Mode. Slice and RoI.
 - in absence of external interfaces (standalone)
 - emulate CPM (input) and ROS/RoiBuilder (output) using Data Source Sink Module (DSS)
 - in conjunction with external interfaces
 - emulate CPM (input) with DSS
 - at CERN with RoiBuilder
 - with ROS Frontend at RAL



Test Setups (1/2)




- Standalone Behaviour
- Events:
 - Vectors pre-loaded in DSS G-link output buffer
 - L1As in bursts distributed through TTC system
- Either:
 - fast flow (no XOFF)
 - regulated flow






Test Setups (2/2)




- Conformance at the interface.

- Test for FIFO empty failure
 - due to flow control
 - LFF driven by ODIN






Fault Status



Fault	Description	Status
DSS-1	S-link destination address counter miscount	Await fix
DSS-2	DAV Glitch	Requires study
DSS-3	Slice value of 4,5 not interpreted correctly	Done
CPSlice-1	<i>CPM-ROD link down on FPGA/TT= 01000/11</i>	Fix awaits test
CPSlice-2	Substatus Word misnumbering.	Done
CPRol-3	FIFO doesn't empty (Flow control fails)	Done
CPRol-4	Channel/Module ID Bits swapped	Done
CPRol-5	BOF in S-Link record seen as BOF00001	s/w artifact
CPSlice-6	S-link LFF enable mask and s/w XOFF have no effect. (Slice operation)	Done
CPSlice-7	Slice readout modes with more than one slice fail.	Done
CPSlice-8.	Bad Sub-status words in multi-slice operation	Done
CPRol-9	Spy buffer registers clear doesn't work	Await Fix
CPSlice-10	Operation fails after initial fragment	Done
CPSlice-11	Parity Error word incorrect	Done




Keeping Track of the Fixes



- Viraj:
 - “I have revisited the QA procedures on how to record the problems and their fixes encountered during module commissioning and testing.
 - There are two form we can use:
 1. Route Card, this will be for recording module specific problems and fixes during initial inspection, testing and operational phase.
 2. Problem Report, (see attached example) to record common design problems and solutions. I believe this will be the appropriate form to use for firmware problems.”



Where Next?



- There is convergence in firmware debugging
- Now, on to the last fix (or is it two ...)
- Test zero suppression thoroughly (RoI/Slice)
- Soak tests (the hard stuff)
 - some errors observed at level of a few per 10,000,000
- Comprehensive test vectors.
- DSS modifications:
 - hardware fragment check
 - wraparound (cycle without s/w intervention.)