

ROD Status

Hardware

- 2nd test crate (ROD+DSS) set up
 - Useful in setting up multi-crate run control s/w
 - Failure of ROD (failure to load firmware) and DSS (output memory not always readable) caused dismantling of set up and return of h/w (under warranty?) to ID
 - New modules under test (Neil) with LabView in H/D lab.

Firmware: CP Data

- Operational ...
- Except
 - Status bits in S-link data need to be checked against spec.
 - A few minor violations of spec.
 - Bit 23
 - Status word zero suppression
 - ...

Firmware: CP Rol

- Operational but flaky
 - Maximum ROI ...
 - 0 = no limit: Right idea but not in the spec.
 - 0x50 results in loss of data
 - Recall: 16 per Glink x 4 = 64 (0x40)
 - Need to check flow control again

Firmware: Cp-CMM Data

- Ambiguities in Interpretation of spec.
 - results in 16 data words for crate merger, 20 data words for system merger. Sub-sums do not appear from crate merger!
 - Need a new data type to define connection
 - Modifications of simulation requested:
 - Provided by SJH but not yet tested
 - Should the spec. be changed?

Firmware: JEM Data

■ Initial Tests:

- Data frames are packed 2 per data word
 - Which frame should be least significant.
 - Spec doesn't specify.
 - Engineer J. chose 1 (from "Frame 0-1")
 - S/W Guru S. chose 0
- Data Frame counter (F0/F1):
 - Implemented in firmware?

Firmware: JEM Rol

- First tests...
 - Rol zero suppression non functional?
 - Simulation s/w (bill-file) lacks 'simple' functionality (or does it?)
 - Patterns...