




ATLAS T1

# GLINK DAV GAP requirement of ROD f/w

Weiming Qian  
UK Meeting, RAL  
06/02/2004



## 3 factors affecting DAV GAP



- GLINK serial data format and SLINK slice data format
- Data FPGA State Machine Design
- Clock domains (GLINK clock .vs. TTC clock40 )

# GLINK data format and SLINK slice data format



- Header and status words adds to the DAV GAP

	1 GLINK slice data length (serial)	1 SLINK slice data length	Ticks needed to write 1 Slink slice to FIFO
6U ROD CPM DAQ	84	84	84
6U ROD JEM DAQ	89	47	80
9U ROD CPM DAQ	84	85	85
6U ROD Neutral	X	X+1	X+1
9U ROD Neutral	X	X+2	X+2




Figure 16: CPM G-Link DAQ data format





Figure 17: CPM S-Link DAQ data format.





# State Machine Simulation 1



- CPM DAQ State Machine with 5 ticks DAV GAP


# State Machine Simulation 2



- CPM DAQ State Machine with 3 ticks DAV GAP




# State Machine Simulation 4



- JEM DAQ State Machine with 21 ticks DAV GAP





# State Machine Simulation 5






- JEM DAQ State Machine with 16 ticks DAV GAP

# State Machine Simulation 6



- JEM DAQ State Machine with 15 ticks DAV GAP

# Clock domains




$2 \text{ ticks of GL\_STRBOUT} < 3 \text{ ticks of clock40} < \mathbf{Tdelay} < 4 \text{ ticks of clock40} < 5 \text{ ticks of GL\_STRBOUT}$


# Minimum DAV GAP for CPM slice data



- Minimize the DAV GAP
  - Optimize State Machine
  - Optimize Timing of interface signals
  - Optimize Flow control




# Neutral Format f/w




- Minimum DAV GAP
  - 5 ticks
  - Recommending 6 ticks
- Test results
  - Works with CPM\_DAQ 1, 2 or 3 slices
  - Works with CPM\_DAQ 4 and 5 slices
    - With new version of Controller f/w

# VMM signal quality



- VME -- signal integrity problem
  - Edges of DS is not good
  - Small step within input transition area of TTL gate
  - Might cause double latch


- Signal traces on VMM
  - Over 20cm
  - Impedance not controlled
  - Impedance on VMM can **NOT** match the impedance on backplane anyway
    - Due to load effect on backplane
    - Bare backplane impedance ~50ohms



# VMM proposals



- Add buffers near backplane connector
  - DS
  - A01 — A23
  - DTACK
  - WRITE
  - SYSRESET
  - Possible for D00 -- D15
- Choose slower buffers
  - 74LS series instead of 74F series
  - Slower but smooth edge is better than faster but glitch edge
- Remove termination on VMM side
  - DS
  - A01 — A23
  - WRITE
  - SYSRESET



# Old TTCDec reset and clock jitter



- To solve DSS clock unstable problem
  - Replace the flying wire from front panel to TTCDec
  - Add a “HUGE” capacitor to the TTCDec reset circuit
    - 5 ~ 10s reset constant, please wait patiently!
  
- CPM GLINK unstable
  - Old TTCdec clock is too jittery to be reference clock for GLINK
  - Redesign old TTCDec and add PLLs to filter clock jitter.
  
- New TTCDec address
  - Initial TTC address: 3FC0h, I2C address: 00h
    - Set by 100Kohms pullup or pulldn resistors on new TTCDec
  - Can be override with 4.7Kohms resistor
    - TTCrx output can drive 1.5Kohms load with only 80mV shift