







## ECAL DEE1 Pedestal Distribution







( Results from ECAL Integration Center)



Comment: All channels electronically are operational

## ECAL DEE1 Pedestal Distribution

(Log scale results from ECAL Integration Center)



Comment: All channel are electronically operational. The tail of the RMS distribution for G12 is due to channels with long connecting cable from the VPT to the mother board.