




Slice Testing


Priorities & Plans



Overview



- ! CP
- . JEP
- PPM!
- ! Backplane
- 9U ROD
- ! Other Modules
- ! Test Beam Synchronisation




CP



· CP

- A few remaining basic issues:
 - Implement a maximum number of CPM configuration.
 - Prepare checklist and revisit it:
 - Timing setup.
 - BCNUM matching.
 - Operation at minimal L1A separation.
 - Multi-slice operation.
- Add a couple of CPMs and we can start some real tests.
- And one of these days, we'll even have a PPM!



JEP




. Await new module:

- Use Jem 0.1 to debug
 - CMM firmware.
 - JET variant, in particular.
 - Rol ReadOut and event matching.

JEM 1.0

- Available Mid May, early June:
 - Time to schedule tests soon.
- Then:
 - Reintegrate with ROD, CMM.
 - When will a 2nd JEM be available?
- Requirements:
 - Software.
 - 1 6u ROD firmware for Rol.
 - G-Link Optical-Electrical converters
- Actual Status in terms of slice-test progress?
 - Snookered.



PPM



Early Front End integration:


- Needs to be scheduled in conjunction with JEM, CPM
- To take place in Mainz ASAP.
- Date to be agreed.

Test beam in June:

- Takes the "front seat"
- This by definition leaves slice tests in the "back seat".

Multiple new PPMs


- Available soon.
 - When will firmware be mature.
 - When will all the software components be available to allow integration?
 - Difficult to schedule when there are not many dates to work from!
 - Middle June?



Backplane



- Backplane working group
 - established after Heidelberg.
 - Request for input from Sam.
 - Not much more activity, yet.
- · Testing.
 - Systematic work to proceed in BRUM.
 - Orthogonal series at RAL?
- ! Repair of bent pins.
 - Not yet demonstrated!




9U Rod



9U ROD

- Just around the corner!
 - Something ready to plug-in in July.
 - Software work needs to start soon.




Other Modules



· TCM & VMM:

- Are there tests which are missing or unfinished?
 - . CAN.
 - Reset functionality.
 - Clock integrity.
 - Dual-port use.



Test Beam Synchronisation



- Commitments start in July:
 - What Testing work can go on in parallel:
 - Largely JEM and 9U ROD. These will likely be late arrivals to the test beam.
 - Systematic CP tests from the "checklist" -
 - As a part of the programme
 - · When beam not available.
 - How to minimise disruption?
 - Do initial DAQ integration with DSS and ROD, as suggested at Heidelberg?
 - Delay shipping date. Then change "mode".